

FIELD INSPECTION REPORT

Date of Inspection : 23.12.20	District: Gaya
Division : Gaya	Length (km):
Name of the Road: L105-Halumatta Road to Sidasuya via Pulgar & Mithiyah	
Scheme/Programme: MAINTENANCE	P. M. G. S. Y.
Package No.: BR-12R-918	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	
No.	Remarks
1. Pavement	
a) Road Junction condition	S/U
b) Condition of Surfacing	S/U
c) Riding Quality	S/U
d) Road Camber	S/U
e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f) Contraction Joints provided or not (CC Pavement)	Yes/No
g) Compaction of flank/slope & raincuts if any	Yes/No
2. Culverts	
a) Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b) Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N.A.
c) Condition of railings/slab/approach for Bridges	S/SRI/U N.A.
3. Road Furniture	
a) Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4. Compliance History	
a) Status of ATR's & any others	No ATR

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME: Harishankar

DESIGNATION: J. E.

Harishankar
23.12.20
(Signature)