FIELD INSPECTION REPORT

Date of h	spection: 2	2-12-2020	District: Patra	
Division: Patra			Length (km):	
Name of	the Road: Pote	a zila Antalgat Kar	ya Pianundat Patta antayat. bra Bhaya Timan Bigla Ki Nisman Karya Jima	Daniyawan furk
Scheme/l	Programme:	MAINTENANCE	Niman Karya 4000	maacy of years) as
- 1887 N. C.		Danizawan	Road Id No .: Nabar	
Status of the Project:		Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/ Maintenance		
Sl. No.	Sales ass	Parameters to	be checked	Remarks
1	Pavement		State	
a)	Road Junction condition			_8/U
b)	Condition of Surfacing			√S/U
c)	Riding Quality			√8/U
d)	Road Camber			√S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRIAU
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			_S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U MA
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No			
Z.	Compliance History			
a)	Status of ATR's & any others			NO
Overall I	Rating :	Pot Repair	work in hogress	

1 -	
Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	
1986.	

NAME: Hi manshu Loj DESIGNATION: 4E