

FIELD INSPECTION REPORT

Date of Inspection: 28/12/20 District: mekanda
 Division: W/169 Length (km): 1.51km
 Name of the Road: Chel Sayang Beshen Road to Belawetha-Jalabi
 Scheme Programme: MAINTENANCE Maintenance
 Package No.: Road ID No.:
 Status of the Project: Ongoing/Completed/Under Maintenance Under maintenance
 Work is a part of: New Connectivity Up gradation/Maintenance maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road surface condition	ST S
b)	Condition of Surfacing	ST S
c)	Riding Quality	ST S
d)	Road Camber	ST S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No Yes
f)	Crackwidth limits provided or not (CC Pavement)	Yes/No Yes
g)	Condition of flankslope & raincuts if any.	Yes/No No
2.	Cross Drainage	
a)	Condition of head walls in Home pipe culverts including its painting	Satisfactory S
b)	Condition of Abutment & Wing walls, Slope in RCC culverts	Satisfactory S
c)	Continuity of drainage fall approach for bridges	Satisfactory S
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Boards less than 20mm stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Noted - LATIC & city others	NO

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Satisfactory

NAME: Francis Kumar Anya


 6-1-21