MMGLY FIELD INSPECTION REPORT

Date of I	nspection . A		CTION REPORT	
Date of Inspection: 05.1.2021 Division: Silamash			District: Silamorti	
Name of the Road: Havibas pus to I			Length (km): 0.ckm	
Scheme/	Programme:	MAINTENANCE	sishsampus	
Package		MAINTENANCE	D. Arrisi	
Status of the Project: Ongoing/Complete Work is a case of: New Connectivity		Ongoing/Complete	Road Id No.:	
		New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked			Remarks
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber S/U			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Yes/No			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any Yes/No			
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/U			
c)	Condition of railings/slab/approach for Bridges S/SRI/U			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4.	Compliance History			
a)	Status of ATR's & any others			

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

The work has not been started yet.

(Signature)

NAME: Mojibultuge.

DESIGNATION: J.B.