## work not completed

## FIELD INSPECTION REPORT

te of In	spection: 06/01/2021 Distr		da
vision:		gili (km):	90.00
		udaik Bhaisan	1 Mura
heme/l'	The state of the s	d Id No.:	
	the Project:   Ongoing/Completed/Unde	The same of the sa	
	case of: New Connectivity/Up grad		
1. No.			Remarks
1.	Pavement		
n)	Rond Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
n	Contraction Joints provided or not (CC Pavement) Yes/No		
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts NA		S/SRI/U
c)	Condition of railings/slab/approach for Bridges N/A		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
#14.F	Compliance History		- 4
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Remarks-OT Surfacing is left in 74.0m. due avillagers hindrance.

(Signature) (Signature)

NAME: RAVI KUMPA

DESIGNATION: fr, Englneer

Scanned with CamScanner