Inspection Report for Flood Damage Work

Date:

- Cryan vibhallow 1. Name of PIUs -
- 2. Name of Block/Road parton parksaul to singward path

A Fer Road

1. Damage Location/Chainage

O. ov Kon 200. 200 lan, O. 600 km, O. 90 lan, 1.2 km, 1.8 km, 2.0 km 2,51cm,

1.2159 1000 2. Damage Length

3. Nature of Damage

4. Details of Restoration Works

Material being used in Restoration works: Brice ball

Equipments/Tools being used in Restoration works: ii.

Procedure taken up in Restoration works: iii.

: 1-21591cm iv. Restored Length

B. For Bridge

- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works
 - Material being used in Restoration works:
 - Equipments/Tools being used in Restoration works: ii.
 - Procedure taken up in Restoration works: iii.
 - Restored Length iv.

Signature of JE/AE/EE

(Name of Inspector)

RWD work DIVISION muzerflasspur Gast-1

GENERAL ABSTRACT

Name of Road

Pahsaul to Singwari Path

District

Muzaffarpur

Block

Katra

Division

Division	Muzaffarpur East-2	2.881 Km
ength of Road (in Km)		AMOUNT (LAKHS)
SI. No.	DESCRIPTION	19.584
1	Jhama metal	0.000
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	19.584
	GRAND SUB TOTAL	19.584
TOTAL	COST OF PROJECT IN LACS =	say 19

say 19.58 Lac

Technically approved for As 19.58 Lac

(Rupees nineteen lac fifty eight thousand only)

AND WOOK CITCLE Muzasfarpus