

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan vibhakar (EE RWD work division muzaffar East-1)
2. Name of Block/Road - minapur / sheehar pmd road to chandehar Rai ke ghar
Hote Hue surjan pateri delandhan Rai ke ghar tak.

A. For Road

1. Damage Location/Chainage : 0.120 km, 0.140 km, 0.180 km, ~~0.200 km~~, ~~0.210 km~~
2. Damage Length : 0.0425 km
3. Nature of Damage :
4. Details of Restoration Works :
- i. Material being used in Restoration works : Brick bats & local sand
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length : 0.0425 km

B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
- i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

Signature of JE/AE/EE


18.11.20
Signature

(Name of Inspector)

EE

RWD work division
muzaffarpur East-1

GENERAL ABSTRACT


Name of Road Sheohar PWD Road to Chandeshwar Rai ke Ghar Hote Huye Surjan Palri Lilardhan Rai Ke Ghar Tak
District Muzaffarpur
Block Minapur
Division Muzaffarpur East-2
Length of Road (in Km) 0.750 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	10.640 8' 12
2	Sand Filling	0.100
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	10.740 8' 22
TOTAL COST OF PROJECT IN LACS =		10.740 8' 22


say 8.22 lac


11/11/2020
JE
RWD


11/11/20
AE
RWD


11/11
EE
RWD

Technically approved for Rs 8.22 lac
(Rupees Eight lac twenty two thousand only)


26-12-20
SE
RWD WORK CIRCLE
MUZAFFARPUR