Inspection Report for Flood Damage Work

-				
D	~	•	n	٠
 _	a	٠	u	٠

- 1. Name of PIUs Gyan vibraleout
- 2. Name of Block/Road Kadra/ Bhadei Chook to Dhanor high School.
- A. Fer Road
- 1. Damage Location/Chainage
- : 0.0 la, 0. 100 lm, 0. 150 lm, 0. 350 lm, 0. 408 lm, 0. 455 lm, 0. 600 lm
- 2. Damage Length
- : 0.336km (0.3355/cm)
- 2 Mature of Danie
- MARIA
- 3. Nature of Damage
- 4. Details of Restoration Works :
 - i. Material being used in Restoration works: Brock buts
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works:
 - iv. Restored Length
- : 0:336 Km Appa
 - (0:3355 Km)

- B. For Bridge
- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works
 - i. Material being used in Restoration works:
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works:
 - iv. Restored Length

Signature of JE/AE/EE

Light ture

(Name of Inspector)

EE

RWD Work DIVLYMM muzerffarper Gast-1

GENERAL ABSTRACT

Name of Road

Bhadai Chowk to Dhanor High School

District

Muzaffarpur

Block

Katra

Division

Muzaffarpur East-2

Length of Road (in Km)

3.476 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
THE WAS COME.	Jhama metal	4.381
2	Sand Filling	0.000
-	Sand bag	0.000
3	Bamboo Piles	0.000
4	GRAND SUB TOTAL	4.381
	OST OF PROJECT IN LACS =	4.381

Say 4:38 lakh

JF

DWD

AE 11.11700

RWD

EE

RWD

Technically approved for RS 4:38 land (Rupees sour land thirty Eight thousand) only

SE

RWD WOOK Crocle

muzastarpur