Inspection Report for Flood Damage Work

-				٠.
11	2	7	n	۰
	u	Ł	•	٠

- 1. Name of PIUs Gyan vibhakar (EE muzastanpur Gat-1)
 2. Name of Block/Road mirabur/ To 2 Belsan puro wouldo tengahi

A. For Road

- 1. Damage Location/Chainage
- : 0.018 km, 0.200 km, 0.350 km, 0.670 km, 0.920 km,
- 2. Damage Length
- : 0.332 Km

1.5 km, 2.0 km

- 3. Nature of Damage
- 4. Details of Restoration Works
 - Material being used in Restoration works:
 - Equipments/Tools being used in Restoration works:
 - ili. Procedure taken up in Restoration works:
 - Restored Length iv.
- : 0.332 km

X B. For Bridge

- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works
 - Material being used in Restoration works:
 - Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works:
 - iv. Restored Length

Signature of JE/AE/EE

(Name of Inspector)

· BE

RWD WORK DIVISION

muzaffarpur Geest-1

GENERAL ABSTRACT

Name of Road

T02 Belsan PWD Road to Tengahi

District

Muzaffarpur

Block

Katra

Ploor

Muzaffarpur East-2

Division Length of Road (in Km)

SI. No.	DESCRIPTION 2.100 Jhama metal	AMOUNT (LAKHS)
	Sand Filling	16.780
$\frac{2}{3}$	Sand bag	0.209
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	0.000
Sept.	COST OF PROJECT IN LACS =	16.989
TOTAL C	,031 01 1 NOSE01 NV EACS =	16.989

say 16.99 lac

Ameg 12/2020

JE

RWD

ASTIMO

ΑE

RWD

EE ON SIN

RWD

Technically approved for RS 16.99 Lac (Rupees sixteen lac ninety nine thousand only)

SE

RWD WOOK CITCLE