Inspection Report for Flood Damage Work Date Name of PIUs- Gyan vibbalcas
Name of Block/Road- (course) prayagrami Chowic to Hathauri 1 2 A For Road Damage Location/Chainage 0. Govin, 0.9501m, 1.201m, 1.501m, 2.001m, 3.001m 1 2 Damage Length 0.3541Km 3 Nature of Damage Details of Restoration Works-4 Material being used in Restoration Works-Brick bats ii Equipments/Tools being used in Restoration Works-Procedure Taken up in Restoration Worksiii iv Restored Length 0.3541cm B. For Bridge 1 Damage Location/Chainage 2 Damage Length 3 Nature of Damage Details of Restoration Worksi Material being used in Restoration Works-

Equipments/Tools being used in Restoration Works-

Procedure Taken up in Restoration Works-

Restored Length

Signature of JE/ AE/ EE

ii

iii

iv

Signature
(Name of Inspector)

RWD WOOK DWISTON MUZENSFASTUS GAST-1

GENERAL ABSTRACT

Name of Road

Prayagwari Chowk to Hathauri

District

Muzaffarpur

Block

Katra

Division

Muzaffarpur East-2

Length of Road (in Km)

8.000 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	9.892
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	9.892
TOTAL C	OST OF PROJECT IN LACS =	9.892

Say 9.89 lac

mille

RWD

A. 11.11.200

RWD

EE

RWD

Technically approved for RS 9-89 lac (Rupees vivne lac sighty nine thousand only)

SE. 12.00

RWD WOOK Crocle