

# Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Enyam vibharkar

2. Name of Block/Road - ~~FE 121~~ / RDO Sdauk se Ussauli' chowk to chandel  
maliya vangi chowk talu.

## ☒ A. For Road

1. Damage Location/Chainage : 0.090km, 0.180km, 0.280km, 0.380km, 0.480km, 0.580km, 0.680km
2. Damage Length : 0.681 Km approx (0.6809 km)
3. Nature of Damage :
4. Details of Restoration Works :
  - i. Material being used in Restoration works : Brack bat
  - ii. Equipments/Tools being used in Restoration works:
  - iii. Procedure taken up in Restoration works :
  - iv. Restored Length : 0.681 km (0.6809 km)  
approx

## ☒ B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
  - i. Material being used in Restoration works :
  - ii. Equipments/Tools being used in Restoration works:
  - iii. Procedure taken up in Restoration works :
  - iv. Restored Length :

Signature of JE/AE/EE

  
21.11.20  
Signature

(Name of Inspector)

EE

RWD work division  
Muzaffarpur Ghat-1

### GENERAL ABSTRACT

Name of Road REO Sadak se Ufrauli Chowk to Changel Mliyavari Chowk Tak

District Muzaffarpur


Block Katra

Division Muzaffarpur East-2


Length of Road (in Km) 1.082 Km

| Sl. No.                         | DESCRIPTION     | AMOUNT (LAKHS) |
|---------------------------------|-----------------|----------------|
| 1                               | Jhama metal     | 16.617         |
| 2                               | Sand Filling    | 0.000          |
| 3                               | Sand bag        | 0.000          |
| 4                               | Bamboo Piles    | 0.000          |
|                                 | GRAND SUB TOTAL | 16.617         |
| TOTAL COST OF PROJECT IN LACS = |                 | 16.617         |

say 16.62 lac



JE  
RWD




AE  
RWD



EE  
RWD

Technically approved for Rs 16.62 lac  
(Rupees sixteen lac sixty two thousand only)



SE  
RWD WORK CIRCLE  
muzaffarpur