

## Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan Vibhakar
2. Name of Block/Road - mirapur / PWD road to Paschim Hazam talo' Hote  
Hue Hazam talo' talik.

### A. For Road

1. Damage Location/Chainage : 0.120 km, 0.200 km, 0.300 km, 0.600 km, 0.700 km, 0.800 km, 0.920 km
2. Damage Length : 0.158 km
3. Nature of Damage :
4. Details of Restoration Works :
  - i. Material being used in Restoration works : brick balls & local sand
  - ii. Equipments/Tools being used in Restoration works:
  - iii. Procedure taken up in Restoration works :
  - iv. Restored Length : 0.158 km

### B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
  - i. Material being used in Restoration works :
  - ii. Equipments/Tools being used in Restoration works:
  - iii. Procedure taken up in Restoration works :
  - iv. Restored Length :

Signature of JE/AE/EE

21.12.20  
Signature

(Name of Inspector)

EE  
RWD work division  
mirapur Galt - 1



### GENERAL ABSTRACT

Name of Road PWD Road to Paschim Hazam Toli Hote Hue *Horizon hotel talic*  
District Muzaffarpur  
Block Minapur  
Division Muzaffarpur East-2  
Length of Road (in Km) 1.000 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	4.447
2	Sand Filling	0.100
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	4.546
TOTAL COST OF PROJECT IN LACS =		4.546

*say 4.55 lac*

*[Signature]*  
17/12/2020  
JE  
RWD

*[Signature]*  
17/12/20  
AE  
RWD

*[Signature]*  
17/12/20  
EE  
RWD

*Technically approved for Rs 4.55 lac  
(Rupees Four lac fifty five thousand only)*

*[Signature]*  
17/12/20  
SE  
RWD work circle  
muzaffarpur