

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan vibhakar (EE muzaffarpur East-1)
2. Name of Block/Road - mirapur / Sukder House to Rambhajan House


A. For Road

1. Damage Location/Chainage : (0.0144km to 0.0556km)
2. Damage Length : 41.2 m (0.412 km)
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works : Brick bats & Local sand
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length : 0.412 km

B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

Signature of JE/AE/EE


18.11.20
Signature

(Name of Inspector)

EE

RWD work Division
muzaffarpur East - 1

GENERAL ABSTRACT

Name of Road Sukdev House to Rambhajan House
District Muzaffarpur
Block Minapur
Division Muzaffarpur East-2
Length of Road (in Km) 0.056 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	3.667
2	Sand Filling	0.078
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	3.746
TOTAL COST OF PROJECT IN LACS =		3.746

By 3.74 lac.

[Signature]
11/11/2020

JE
RWD

[Signature]
11/11/20

AE
RWD

[Signature]
11/11

EE
RWD

Technically approved for Rs. 3.74 lac (Rupees
three lac seventy four thousand only)

[Signature]
SE 22/12/20

RWD WORK CIRCLE
muzaffarpur