Inspection Report for Flood Damage Work

~		•	4.5	٠.
D	~	٠	13	•
,,	а	1	•	

- 1. Name of PIUs Chyan vibharkard
- 2. Name of Block/Road Kadsa/ Kenssa Bothma road Hass chandhos! Ke ghar to
 Ambediers Magas Hote Hur se readra Run tak;

A. Fer Road

- 2. Damage Length

: 1.2781cm (APRIL)

a.g. other, 1.20/cm, 1.27756

- 3. Nature of Damage
- >> 1.27756 KM
- 4. Details of Restoration Works
 - i. Material being used in Restoration works: Geratutilling
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works:
 - iv. Restored Length

: 1.278 Km APPROX (1-29+866/Cm)

X B. For Bridge

- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works
 - Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works:
 - iv. Restored Length

Signature of JE/AE/EE

i ight ure

(Name of Inspector)

RWD WMC DIVISION MUZASSENDEN GOLD -1

GENERAL ABSTRACT

Name of Road

Katra Bathna Road HariChoudhary ke Ghar to Ambedkar Nagar Hote Hue se Katra Ran Tak

District

Muzaffarpur

Block

Katra

Division

Muzaffarpur East-2

Length of Road (in Km)

1.300 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Construction of Subgrade and Earthen Shoulders	6.537
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	6.537
TOTAL C	COST OF PROJECT IN LACS =	6.537

Say 6.54 lac

IF

RWD

M. 28.10200

AE

RWD

RWD

Technically approved for RS 6.54 lac (Rupees six lue fifty four thousand only)

SE

RWD WOOK Crocle