Inspection Report for Flood Damage Work

•		_		-	
- 1	1	0	۲	"	
	_	a	٠	v	١

- 1. Name of PIUs Chyan vibhallow
- 2. Name of Block/Road Kenter Anguntur to Chewinbus

A. Fer Road

- 1. Damage Location/Chainage : orolly or look, or sook, 1. with, 2 costs, 3 sol, 4 costs
- 2. Damage Length : 1-98741Cm
- 3. Nature of Damage
- 4. Details of Restoration Works
 - i. Material being used in Restoration works: Brock beds
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works:
 - iv. Restored Length : 1-9874 cm

B. For Bridge

- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works
 - i. Material being used in Restoration works:
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works:
 - iv. Restored Length

Signature of JE/AE/EE

21.11. 20

Light dire

(Name of Inspector)

13/5

RWD WOOK DWILTON murentfasour call-1

GENERAL ABSTRACT

Name of Road

Anyanpur to Chainpur

District

Muzaffarpur

Block

Katra

Division

Muzaffarpur East-2

Length of Road (in Km)

4.673 Km

Length o	f Road (in Km)	AMOUNT (LAKHS)
SI. No.	DESCRIPTION	29.147
1	Jhama metal	0.000
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	29.147
	GRAND SUB TOTAL	29.147
TOTAL C	COST OF PROJECT IN LACS =	Sale 901

Say 29.15 lac

Range Proposo

JE RWD

H. 11.10-L

RWD

EE

RWD

Technically approved for RS 29.15 lac (Rupeel twenty nine lac fifteen thousand only)

SE

RWD WOOK Crocle