Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Cryan vibhaceer

2. Name of Block Road - Kadsa / Ram Khangura to Khanguralih

K. For Road

1. Damage Location/Chainage

: 0.0 lm for trolm, 0-200 lm, 0, 300 lm, 0, 300 lm, 0, 400 lm, 0, 500 pen

2. Damage Length

: 0.346Km

0-600km

3. Nature of Damage

4. Details of Restoration Works

i. Material being used in Restoration works: Boscue bads

ii. Equipments/Tools being used in Restoration works:

iii. Procedure taken up in Restoration works:

iv. Restored Length

: 0-346 Km Alpon (0.34595 Km)

B. For Bridge

1. Damage Location/Chainage

2. Damage Length

3. Nature of Damage

4. Details of Restoration Works

i. Material being used in Restoration works:

ii. Equipments/Tools being used in Restoration works:

iii. Procedure taken up in Restoration works:

iv. Restored Length

Signature of JE/AE/EE

: ith ure

(Name of Inspecto-)

BE

RWD WORK DIMBYON

muzassar pro Gost

GENERAL ABSTRACT

Name of Road

Ramkhangwra to Khanguradih

District

Muzaffarpur

Block

Katra

Division

Muzaffarpur East-2

SI. No.	Road (in Km) 1.900 DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	3.622
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
-	GRAND SUB TOTAL	3.622 3.622

Say 3.62 lac

JE

AE 11.11-20

RWD

EE

RWD

Technically approved for RS 3.62 lac (Rupeel Three lac sixty two thousand only)

SE

RWD WOOK CHARLE

Muzasfarpur