Inspection Report for Flood Damage Work

Date:

- 1. Name of PIUs Cryan vibhancar
- 2. Name of Block/Road Katha Bathari to sish warra

A. Fer Road

- 1. Damage Location/Chainage -0.002014m 0.03014m, 0.1014m, 0.2014m, 0.3014m, 0.3014m, 0.3014m, 0.3014m, 0.3014m
- 2. Damage Length : 0. 1765 lm
- 3. Nature of Damage : 0-176516m
- 4. Details of Restoration Works
 - i. Material being used in Restoration works: Brick hall flow sand
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works:
 - iv. Restored Length
- : 01/265/LM

B. For Bridge

- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works
 - Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works:
 - iv. Restored Length

Signature of JE/AE/EE

ight lire

(Name of Inspector)

EE

RWD work pinchen mirror famping

Cast-1

GENERAL ABSTRACT

Name of Road

Bakhari to Siswara

District

Muzaffarpur

Block

Katra

TOTAL COST OF PROJECT IN LACS =

Division

Muzaffarpur East-2

Lenath of	Road (in Km) 5.166	
SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	5.307
2	Sand Filling	0.381
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	5.689

RWD

Technically approved for R8 5.69 lakh
(Rupees five lakh staty nine thousand only)

SE

RWD WOOK CIRCLE

Muzasfarpur