

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Cryam nibhakar

2. Name of Block/Road - Kerap/Korari Barga Lakhanpur to Baghara Path

A. For Road

1. Damage Location/Chainage : 0.01km, 0.200km, 0.800km, 1.501km, 2.001km, 2.901km, 4.01km
2. Damage Length : 1.9974km
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works : Brickbat
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length : 1.9974km

B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

Signature of JE/AE/EE

21.11.20
Signature

(Name of Inspector)

EG

RWD work Division
Muzaffarpur East -1

GENERAL ABSTRACT

Name of Road Koriari Baigna Lakhanpur to Bagbasa Path

District Muzaffarpur

Block Katra


Division Muzaffarpur East-2

5.400 Km


Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	21.300
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	21.300

TOTAL COST OF PROJECT IN LACS =


say 21.30 lac


11/11/2020


JE
RWD


11.11.2020

AE
RWD


11/11
EE
RWD

Technically approved for Rs 21.30 lac
(Rupees Twenty one lac thirty thousand only)


2.12.20
SE

RWD WORK CIRCLE
MUZAFFARPUR