FIELD INSPECTION REPORT

•			1 00		
Date of Inspection: 25.12-2020			District: W. chambaran		
Disdelan . O II . I			Length (km): 2.0		
Name of	the Road: Los	7-Loss Sex	hotolito Malantolu		
Scheme/Programme: MAINTENANCI		MAINTENANC			
Package No.: BR. 37R- 424		R. 424	Road Id No.: 318088 02195		
Status of the Project: Ongoing/Completed/Under Maintenance UNDBR N				Main	
Work is a case of: New Connectivity/			ity/Up gradation/ Maintenance Ma	177	
83-Mo	Faremeter to be checked /4 Remarks			Remarks	
1	Parament			i	
a)	Road Junction	condition	S	-8/U	
b)	Condition of Surfacing			∽S/U	
c)	Riding Quality			S/U	
d)	Road Camber	<u> </u>		S/U	

g)	Compaction of flank/slope & raincuts if any	yu Yes/No
*	Cross Brainage	i .

Whether free from defects such as visible cracks, exposed

aggregates in case of CC Pavement.

Contraction Joints provided or not (CC Pavement)

Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/U 6) S/SRI/U

Condition of head walls in Hume pipe culverts including its painting

Condition of railings/slab/approach for Bridges c) 3. Road Furniture

Whether sign boards/informatory/cautionary Board/km & 200m Yes/No a) stones/Pavement road markings are provided and maintained Compliance History 4

Status of ATR's & any others a)

Overall Rating

c)

f)

a)

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

HO . .

Yes/No

Yes/No

S/SRI/U

N/A

(Signature)

NAME: SUNCL BUNAR

designation: J'E