

FIELD INSPECTION REPORT

Date of Inspection : - 03/12/2020	District: - Nalanda
Division : - Hilsa	Length (km): - 1.0 km
Name of the Road: - Baligoraia to Nonaibigha near Krishnabigha	
Scheme/Programme: MAINTENANCE	
Package No.: - 4515(MNP)	Road Id No.: -
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Rating
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls. Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Sumis of ATR's & any others	

Elevations & Depressions are found many places in the road.

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—



Samsung Quad Camera

Shot with my Galaxy S21

Ganesh Kumar Maundil.

NAME:

(Sign):

3/12/2020
KE