



FIELD INSPECTION REPORT

Date of Inspection : 3.12.20	District: Aurangabad
Division : Aurangabad	Length (km): 6.900 Km
Name of the Road: To 9 to Doman Bishu	
Scheme/Programme: MAINTENANCE	
Package No.: BR02R-753	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition	S	S/U
b)	Condition of Surfacing	S	S/U
c)	Riding Quality	S	S/U
d)	Road Camber	S	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	No	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	yes	Yes/No
g)	Compaction of flank/slope & raincuts if any	No	Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S	S/SRI/U
b)	Condition of Abutment & Wing walls. Slab in RCC culverts	-S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	-S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained		No
4.	Compliance History		
a)	Status of ATR's & any others		Maintenance Board not found Raincuts found in place

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	


 3.12.20
 (Signature)


NAME: