FIELD INSPECTION REPORT

_	The second secon		to Serbawadi tola	
	heme/Programme: MAINTENANC ackage No.: atus of the Project: Magoing/Comple		Road Id No.:	
100000000000000000000000000000000000000				
	a case of:		y/Up gradation/ Maintenance	
Sl. No.	a. Parameters		to be checked	Remarks
1.	Pavement	MASSE BE		
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
n	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4.	Compliance	Compliance History		
a)	Status of AT	Status of ATR's & any others		

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

Remarki - Work in Progress.

VIKAS KUMAR NAME:

DESIGNATION: A £