FIELD INSPECTION REPORT

Date of Inspection: \emptyset	7/01/2021 D	istrict: Patua	
Division: Danapur		ength (km): 4010 km	and the second of the second o
	H30 to Bichlli	' sadak upto Ta	ta colon
Scheme/Programme:	MAINTENANCE	Mainte	(
Package No.:		oad Id No.:	
Status of the Project:		ider Maistenance under	Maintena
Work is a case of:	New Connectivity/Up g	radation/ Maintenance	
Sl. No.	Parameters to be	checked	Remarks
1: Pavement			
a) Road Junction	Road Junction condition		
b) Condition of S	Condition of Surfacing		
c) Riding Quality	Riding Quality		
d) Road Camber	Road Camber		
e) Whether free aggregates in	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f) Contraction Jo	Contraction Joints provided or not (CC Pavement)		
g) Compaction o	Compaction of tlank/slope & raincuts if any		
2. Cross Draina	ge jaga — planeta esta	gradina di Karana di Karana di Karana di K	
a) Condition of l	Condition of head walls in Hume pipe culverts including its painting		
b) Condition of A	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c) Condition of r	Condition of railings/slab/approach for Bridges		
3. Road Furnitu	Road Furniture		
	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4. Compliance I	listory		
a) Status of ATR	's & any others	No	ATR

Overall Rating :

Satisfactory (S)	5 V
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

DESIGNATION:
(SC 4NGH)

(Signature)