

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Cyan vibhakar

2. Name of Block/Road - ICATRA / RCO SARAK VIKHUNPUR to Dami'rai

A. For Road

1. Damage Location/Chainage : 0.300 , 0.450
2. Damage Length : 0.3215 km
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works : Brick bed
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length : 0.3215 km

B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

Signature of JE/AE/EE

21-11-20
Signature

(Name of Inspector)

EE

RWD WORK DIVISION
MUZAFFARPUR EAST - I

GENERAL ABSTRACT

Name of Road REO Sarak Vishunpur to Dani Rai

District Muzaffarpur

Block Katra

Division Muzaffarpur East-2


Length of Road (in Km)


1.169 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
		6.729
1	Jhama metal	0.000
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	6.729
TOTAL COST OF PROJECT IN LACS =		6.729


say 6.73 lac


JE
RWD


AE
RWD


EE
RWD

Technically approved for Rs 6.73 lac
(Rupees six lac seventy three thousand only)


SE
RWD WORK CIRCLE
MUZAFFARPUR