## FIELD INSPECTION REPORT

Sch	me of the Road: Pakk, Pote Dubertura & Cross & come Programme: MAINTI NANCE 1515/Placet	-	
Part	care No.1		
Smith	is of the Project: Ongoing Completed/Under Maintenance k is a case of: New Connectivity/Up gradation/ Maintenance		
SL N	Poyameters to be checked		Remarks
	Pavement		
L	Road Junction condition	5	\$70
83	Condition of Surfacing	5	SALI
151	Riding Quality	5	SIL
(0)	Road Camber	5	Siti
d)	Whether free from defects such as visible cracks, e aggregates in case of CC Pavement.		Yes/No
0	Contraction Joints provided or not (CC Pavement)	-	Yes/No
g)	Compaction of flank/slope & raincuts if any Reserved		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its	ainting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	-	S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m	Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		HOATI

Satisfactory but requires Improvement (\$RI) Unsatisfactory (U)

Pusykan Praval Anti-confinen

(Signature)

NAME: