## FIELD INSPECTION REPORT

District: Vaishali Date of Inspection : 15-01.2020 Length (km): Division: Name of the Road: Mahua Singhkai P.A. Samastipur Mukhra Marg Me kurah Nurshing Scheme/Programme: MAINTENANCE Home Se to uttan ki Awa Braham Asthan Hote Hue MAINTENANCE Scheme/Programme: Road Id No .: Package No .: Ongoing/Completed/Under Maintenance Status of the Project: New Connectivity/Up gradation/ Maintenance Work is a case of: Remarks Parameters to be checked SI. No. Pavement 1. S/U Road Junction condition a) S/U Condition of Surfacing b) S/U Riding Quality c) S/U Road Camber d) Whether free from defects such as visible cracks, exposed Yes/No e) aggregates in case of CC Pavement. Yes/No Contraction Joints provided or not (CC Pavement) f) Yes/No Compaction of flank/slope & raincuts if any g) 2. Cross Drainage Condition of head walls in Hume pipe culverts including its painting √S/SRI/U a) b) Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/U H.A Condition of railings/slab/approach for Bridges S/SRI/U c) 3. Road Furniture Whether sign boards/informatory/cautionary Board/km & 200m Yes/No a) stones/Pavement road markings are provided and maintained 4. Compliance History Status of ATR's & any others a)

Overall Rating

Satisfactory (S) Satisfactory but requires Improvement (SRI)	S
Unsatisfactory (U)	

B.15.39

95/04/221 AE.

(Signature)

NAME:

DESIGNATION: