

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan vibhakar
2. Name of Block/Road - Kedar / Budhara to Badhara


A. For Road

1. Damage Location/Chainage : 0.100km, 0.200km, 0.300km, 0.800km, 0.850km, 1.0km, 1.20km
2. Damage Length : 0.153km
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works : Brick bats
 - ii. Equipments/Tools being used in Restoration works :
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length : 0.153km

B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works :
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

Signature of JE/AE/EE


21-11-20
Signature

(Name of Inspector)

EE

RWD work division
muzaffarpur 6087-1

GENERAL ABSTRACT

Name of Road Budkara to Bhatwara

District Muzaffarpur

Block Katra

Division Muzaffarpur East-2

Length of Road (in Km)

1.335 Km


Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	3.320
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	3.320
TOTAL COST OF PROJECT IN LACS =		3.320

say 3.32 lac




JE

RWD



AE


RWD



EE

RWD

Technically approved for Rs 3.32 lac
(Rupees Three lac thirty two thousand only)



SE

RWD WORKCIRCLE
MUZAFFARPUR