Inspection Report for Flood Damage Work

Date:

- 1. Name of PIUs Gyan Vibrakero
- 2. Name of Block/Road Kerta / To 6 to Berral
- A. Fer Road
- 1. Damage Location/Chainage : 0. 400 lm, 0 500 lm, 0.530 lm, 0.600 lm, 0.700 lm, 0 300 lm
- 2. Damage Length : 0 1|5|6m (0.1146| 6m)

 3. Nature of Damage (146m)
- 4. Details of Restoration Works
 - i. Material being used in Restoration works: Brick ball
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works:
 - iv. Restored Length : Oill Silm (oill 616 1cm)
- B. For Bridge
- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works
 - Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works:
 - iv. Restored Length

Signature of JE/AE/EE

Light ture

(Name of Inspector)

BE

Rur work pivishon muzasfarpur Gast-1

GENERAL ABSTRACT

Name of Road

T06 to Berai

District

Muzaffarpur

Block

Katra

Division

Muzaffarpur East-2

Length of Road (in Km)

2.350 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
. 1	Jhama metal	1.318
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	SUB TOTAL OF INTIAL RECTIFICATION	1.318
	GRAND SUB TOTAL	1.318
TOTAL C	OST OF PROJECT IN LACS =	1.318

Say 1.32 lac

JE

ΑE

RWD

EE

RWD

Technically approved for RS 1.32 lac (Rupees one lac thirty two thousand only)

SE RWD WOOK CITCLE MUZAJFARDUN