

## Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan vibhakar

2. Name of Block/Road - mirapur / Belsand PWD road to Rami Kharsa via Chako Chapsa

✓ A. For Road

- ✓
1. Damage Location/Chainage : 0.400km, 0.450km, 0.500km, 0.5281km, 1.001km, 1.20m, 1.90km
  2. Damage Length : 0.4124 km
  3. Nature of Damage :
  4. Details of Restoration Works :
    - i. Material being used in Restoration works : Brick ball
    - ii. Equipments/Tools being used in Restoration works:
    - iii. Procedure taken up in Restoration works :
    - iv. Restored Length : 0.4124 km

X B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
  - i. Material being used in Restoration works :
  - ii. Equipments/Tools being used in Restoration works:
  - iii. Procedure taken up in Restoration works :
  - iv. Restored Length :

Signature of JE/AE/EE

Signature  
12.12.20

(Name of Inspector)

EE

RWD WORK DIVISION  
Muzaffarpur East-1



## GENERAL ABSTRACT

Name of Road	Belsand PWD Road to Rani Khahira Via Chako Chhapra
--------------	--

District Muzaffarpur

Block	Minapur
-------	---------

Division Muzaffarpur East-2

Division Muzaffarpur East-2 2.700 Km  
 Length of Road (in Km)

Length of Road (in Km)		AMOUNT (LAKHS)
Sl. No.	DESCRIPTION	
1	Jhama metal	13.908
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	13.908
TOTAL COST OF PROJECT IN LACS =		13.908

Say 13.91 lac

JE  
RWD

AE  
RWD

EE  
RWD

Technically approved for Rs 13.91 lac  
(Rupees Thirteen lac ninety one thousand only.)

SE

RWD work circle  
muzaffarpur