

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - *Cyan vikharas*
2. Name of Block/Road - *mira pur / Baswal Bazar to Balwan malah tehatik.*

A. For Road

1. Damage Location/Chainage : *0.500km, 0.700km, 0.850km, 0.960km*
2. Damage Length : *0.1215km*
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works : *Grill beds & Local sand*
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length : *0.1215km*

B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

Signature of JE/AE/EE

[Signature]
18/11/20
i.i.i.i.i.i.i.i

(Name of Inspector)

EE

RWD work division

muzaffarpur East -1

