FIELD INSPECTION REPORT

| | I ILLE HIOLE | | | | |
|--|--|--|---------|--|--|
| Date of Inspection: 26/12/11 | | District: Samastipur | | | |
| Division: RWD Dalsinghsarai Length(km | | Length(km): 1.500 | | | |
| - | e of Road: Tes to Piparporte | | | | |
| Scheme / Programme: MAINTENANCE | | | | | |
| _ | Package No: Road Id No: GTSNY | | | | |
| - | Status of the Project: Ongoing Completed/Under Maintenance | | | | |
| Work is a case of: New Connectivity/ Up gradation/ Maintenance | | | | | |
| Sl. | Parameters to be C | | Remarks | | |
| 1 | Pavement | | | | |
| (a) . | , Road Junction Condition | | SRI | | |
| b) | Condition of Surfacing | | SRI | | |
| (2) | Riding Quality | The Table of the Control of the Cont | | | |
| 3) | Road Camber | | S | | |
| 0) | Whether free from defects such as visible cra aggregates in case of CC Pavement | cks, exposed | SRI | | |
| 0 | Construction Joint provided or not(CC Pavement) | | | | |
| 12 | Compaction of flank/slope & raincuts if any | | U | | |
| 2 | Cross Drainage | | | | |
| (3) | Condition of head walls in Hume pipe culvert including its painting | S | SRI | | |
| 6 | Condition of Abutment & Wing walls, Slab is | n RCC culverts | *** | | |
| (3) | Condition of railings slab approach for Bridge | 0 | | | |
| 3 | Read Furniture | | | | |
| a) | Whether sign boards/information/cautionary I stones/Pavement road markings are provided a | AND THE RESERVE OF THE PARTY OF | 5 | | |
| 4 | Compliance History | | | | |
| 3) | Status of ATR's & any others | | | | |
| | | | | | |

Overall Rating

| Satisfactory(S) | |
|--|-----|
| Satisfactory but requires Improvement(SRI) | SRI |
| Unsatisfactory(U) | |

Alista (Signature) XX

NAME: Despor Changes Sinta DESIGNATION: J-E