FIELD INSPECTION REPORT

Date of	Inspection: \	0/2021	District: Us-Cheropera	The same of the sa
Divisio	is grand :	Constitues	Length (km): 19	
Name (of the Road: 🚫	om 70/1 40 6	esfugicilong	
Scheme	e/Programme:	MAINTENANCE		
Packag			Road Id No.: 380880 140	2_
Status of the Project: Ongoing/Completed/U				
Work i	s a case of:	New Connectivity/Up	gradation/ Maintenance	
St. No.	Parameters to be checked		e checked	Remarks
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage		And the second	
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U

Condition of Abutment & Wing walls, Slab in RCC culverts

stones/Pavement road markings are provided and maintained

Whether sign boards/informatory/cautionary Board/km & 200m

Condition of railings/slab/approach for Bridges

Overall Rating

b)

c)

3.

n)

4.

a)

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	<u>S</u>
Unsatisfactory (U)	

(Signature)

S/SRI/U

S/SRI/U

Yes/No

NO

NAME: Podroto Porsug

Road Furniture

Compliance History

Status of ATR's & any others

DESIGNATION: 3-12