FIELD INSPECTION REPORT

BLOCK- talofpur

Date of Inspection: 08.01.2021			2 13 11 11	hopoa)	
Division: chapog - 2			Length (km): 3.900 Km	his house	
Name of	the Road: N	1-85 to NH10	I Ke Bich Sambota	me howe	
Scheme/	Programme:	MAINTENANCE	/		
Package No.:			Road Id No.:		
Status of the Project: Work is a case of:		Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance Remarks			
					Sl. No.
1.	Payement				
a)	Road Junction condition			✓ S/U	
b)	Condition of Surfacing			S/U 🗸	
c)	Riding Quality			S/U 🗸	
<u>d)</u>	Road Camber			✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			√Yes/No	
g)	Compaction of flank/slope & raincuts if any			/Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/NoV	
4.	Compliance l				
a)	Status of ATR's & any others			NO ATR	

Overall Rating

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME: Mritaijon Kumar_
DESIGNATION: (J.E)

: