

FIELD INSPECTION REPORT

Date of Inspection: 21.12.2020

District: East Champaran

Division: Chakia

Length (Km): 1.655 Km

Name of the Road: Champaran Talbandh to Magharica

Scheme/Programme: MAINTENANCE

Package No.:

Road ID No.:

Status of the Project:

Ongoing/Completed/Under Maintenance

Work is a case of:

New Connectivity/Up Gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	U
c)	Riding Quality	U
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	408
f)	Contraction Joints provided or not (CC Pavement)	408
g)	Compaction of flank/slope & raincuts if any	408.
2.	Cross Drainage	Damage
a)	Condition of head walls in Hume pipe culverts including its painting	SRI
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	Broken
c)	Condition of railings/slab/approach for Bridges	Broken
3.	Road Furniture	SRI
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	SRI
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)

Satisfactory but requires improvement (SRI)

Unsatisfactory (U)

U

Not -> Road is damaged due to flood 2020.

(Signature) 21.12.2020

NAME: Arun Kumar Chakraborty

DESIGNATION: S-1