

FIELD INSPECTION REPORT

Date of Inspection : 11.01.2021
 Division : H/189 District : Nagpur
 Name of the Road : L156 to Dado Bigha Length (km): 0.550 km
 Scheme/Programme : MAINTENANCE
 Package No.: BR-242-139 Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
---------	--------------------------	---------

1. Pavement

a)	Road Junction condition	
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓ S/U
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No

2. Cross Drainage

a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/ N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/

3. Road Furniture

a)	Whether sign boards/informatory/cautionary Board/km & 100m stones/Pavement road markings are provided and maintained	✓ Yes/No
----	--	----------

4. Compliance History

a)	Status of ATR's & any others	NO ATR
----	------------------------------	--------

Overall Rating :

Satisfactory (S)	- S -
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

Ramprakash Chaudhary

Ramprakash Chaudhary
 11.01.2021
 (Signature)