## FIELD INSPECTION REPORT

Date	of Inspection: 16/12/20   District: Bhagalpur	PROPERTY.	
Divisi	on : Bhagalpur   Length (Km) :		Carrier Co
Name	of the Road: REO Poth Radharagen to Muslim Tole	a and Das Tu	a
Schem	e/Programme:   MMOSY (UEN)		
Packag	e No.:   Road Id No.: 207	692 12	026
Status o	of the Project:   Ongoing / Completed / Under Maintenance	2 2	Z X W
Work is	s a case of:   New Connectivity / Up gradation / Maintenan	ice	
SL. No. Parameters to be checked		Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Qualify	S/U	7.18 S
d)	Road Camber	S/U	N.
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes / No	
g)	Cpmpaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage	1007110	# # # # # # # # # # # # # # # # # # #
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U	
;)	Condition of railings/slab/approach for Bridges	S/SRI/U	nla
	Road Furniture	A CAMP	· 大大學
)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes/No	
	Compliance History		
) !	Status of ATR's & any others		
all Rat	ing:		
	Satisfactory (S)		
	Satisfactory but requires Improvement (SRI)	SRI	7
	Unsatisfactory (U)	3/1	
	Unsatisfactory (U)		

Note: Road furniture repainting reasured

NAME: NEERAJ KUNAR

DESIGNATION: JE

Signature Signature