

# FIELD INSPECTION REPORT

Date of Inspection : 16/12/20		District : Bhagalpur	
Division : Bhagalpur		Length (Km) : 2.740	
Name of the Road : Dauna to Hanjan Tola (Nobrai)			
Scheme / Programme :		MMWSY (SC)	
Package No. :		Road Id No. : 20703213024	
Status of the Project :   Ongoing / Completed / Under Maintenance			
Work is a case of :   New Connectivity / Up gradation / Maintenance			
SL. No.	Parameters to be checked	Remarks	
1.	<b>Pavement</b>		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Cmpaction of flank/slope & raincuts if any	Yes/No	
2.	<b>Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	<b>Road Furniture</b>		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes/No	
4.	<b>Compliance History</b>		
a)	Status of ATR's & any others		
<b>Overall Rating :</b>			
Satisfactory (S)			
Satisfactory but requires Improvement (SRI)		SRI	
Unsatisfactory (U)			

Note : Sign boards needs painting , Km & 200m stone repainting & fixing .

NAME : NEERAJ KUMAR  
DESIGNATION : JE

16/12/20  
Signature