

FIELD INSPECTION REPORT

Date of Inspection : 06.1.21	District: Gitaamashi
Division : Beland.	Length (km): 0.150
Name of the Road: Magendon Ray house to Raja Dheng PWD Path	
Scheme/Programme: MAINTENANCE	GTSNY
Package No.:	Road ID No.
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S
b)	Condition of Surfacing	✓ S
c)	Riding Quality	✓ S
d)	Road Camber	✓ S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes
g)	Compaction of flank/slope & raincuts if any	✓ Yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its protection	✓ S/SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI
c)	Condition of railings/slab/approach for bridge	✓ S/SRI
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stone/Pavement road markings are provided and maintained	✓ Yes
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	✓
Satisfactory but requires Improvement (SRI)	X
Unsatisfactory (U)	Y

Spsh
6.1.21
(Signature)

NAME: Ginish Prasad Sen

DESIGNATION: JE RWD Beland