## Inspection Report for Flood Damage Work

Date:-Gyan vibrakar 2 Name of Block/Road: - Agamawli to therma Bridge over old Bagmati Ever (majghed) (A) For Road: X 1. Damage Location/Chainage :- a820m 0.082 km 2. Damage Length 3. Nature of Damage :-4. Details of Restoration Works: Material being used in Restoration works:- Brick bots. (i) Equipment's/Tools being used in Restoration works:-(ii) (iii) Procedure taken up in Restoration works: :- 0.082 km Restored Length (iv) (B) For Bridge: \ :- 0.900 km, 0.200 h 1. Damage Location/Chainage :- 0.082 km 2. Damage Length 3. Nature of Damage 4. Details of Restoration Works: (i) Material being used in Restoration works:- ゆかに bats・3 bamboo. (ii) Equipment's/Tools being used in Restoration works:-(iii) Procedure taken up in Restoration works:-:- 0:082 Km (iv) Restored Length

Signature of JE/AE/EE

Signature
(Name of Inspection)

EE RWD work Division myzaffarbus East-L

## **GENERAL ABSTRACT**

Name of Road

Hit Bridge on Repair of Road-from Ramauli to Tharma pood over old Bagmati River.

District

Muzaffarpur

Block

Gaighat

Division

Muzaffarpur East-2

Length of Road (in Km)

8.320 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	9.452
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.578
1	GRAND SUB TOTAL	10.029
TOTAL C	OST OF PROJECT IN LACS =	10.029

Says = 10.03 lac

RWD

**RWD** 

/ RWD

technically Approved for Ps. 10.03 lac ( Rubees ten Lac three thousand only)

RWD Work circle muzaffax bux