

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan vibhakar

2 Name of Block/Road :- maithi pmasi road to maithi horizon tola (haighat)

(A) For Road:✓

1. Damage Location/Chainage :- 0.025km, 0.900km, 1.10km, 130km, 1.5km (1.8km length)
2. Damage Length :- 272.68m
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- Brick bats
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 0.272 km.

✗ (B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)

EE

RWD work Division
muzaffarpur East-1

GENERAL ABSTRACT

Name of Road Maithi PMGSY Road to Maithi Harijan Tola

District Muzaffarpur

Block Gaighat

Division Muzaffarpur East-2

Length of Road (in Km) 1.825 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	5.769
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	5.769
TOTAL COST OF PROJECT IN LACS =		5.769

Says 5.77 lac

[Signature]
7/12/20
JE
RWD

[Signature]
7/12/20
AE
RWD

[Signature]
09/12
EE
RWD

Technically Approved for Rs 5.77 lac
(Rupees five lac seventy seven thousand only).

[Signature]
09.12.20
SE
RWD work circle
muzaffarpur.