Inspection Report for Flood Damage Work

Date.: 26/12/2010
1. Name of PIUs - Executive Engineer, R.W.D., Works, Division, Muzaffarpur West
2. Name of Block – Sahebganj
3. Name of Road/Bridge - Baijnathpur H.E. School To Madhopur
A. for Road
1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works : Bricer gust & alcer a
i. Material being used in Restoration works:
ii. Equipments/Tools being used in Restoration Works:
iii. Procedure taken up in Restoration works:
iv. Restored Length:
B. for Bridge
1. Damage Location/Chainage : (
2. Damage Length : \\
3. Nature of Damage :
4. Details of Restoration Works :
i. Material being used in Restoration works:
ii. Equipments/Tools being used in Restoration Works:
*

iii. Procedure taken up in Restoration works:

iv. Restored Length:

R.W.D. Works Division, Muzaffarpur west

(Name of Inspector)