

Inspection Report for Flood Damage Work

Date.: 26/12/2010

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West

2. Name of Block – Sahebganj

3. Name of Road/Bridge – Extension of Baijnathpur H.E. School To Madhopur Hagari Path

A. for Road

1. Damage Location/Chainage : 500m to 1800m

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works : Grnd road crust with sub-grade should be embedded in concrete

i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration Works : Brick Bricks & alls

iii. Procedure taken up in Restoration works : Tractor, SCB etc

iv. Restored Length :

B. for Bridge

1. Damage Location/Chainage : N/C

2. Damage Length : N/C

3. Nature of Damage : N/C

4. Details of Restoration Works : N/C

i. Material being used in Restoration works : N/C

ii. Equipments/Tools being used in Restoration Works : N/C

iii. Procedure taken up in Restoration works : N/C

iv. Restored Length : N/C

S
J.E.
26/12/2010

A
A.E.
26/12/2010

K
Executive Engineer,
R.W.D. Works Division,
Muzaffarpur west

G
Signature
(Name of Inspector)