

## Inspection Report for Flood Damage Work

Date.: ..... 26/12/2020

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West

2. Name of Block – Sahebganj

3. Name of Road/Bridge – Manain To Bangra Barar Path

A. for Road

1. Damage Location/Chainage : 75000 1.2 km

2. Damage Length : 32m

3. Nature of Damage :

4. Details of Restoration Works : Bricks & sand filling

i. Material being used in Restoration works : —

ii. Equipments/Tools being used in Restoration Works : Pickaxe & TCB etc

iii. Procedure taken up in Restoration works : —

iv. Restored Length :

B. for Bridge

1. Damage Location/Chainage : —

2. Damage Length : —

3. Nature of Damage : Nil


4. Details of Restoration Works : —


i. Material being used in Restoration works : —


ii. Equipments/Tools being used in Restoration Works : —


iii. Procedure taken up in Restoration works : —

iv. Restored Length : —

  
J.E.

  
A.E.

  
Executive Engineer,  
R.W.D. Works Division,  
Muzaffarpur west

  
Signature  
(Name of Inspector)