

## FIELD INSPECTION REPORT


|                        |                                            |              |            |
|------------------------|--------------------------------------------|--------------|------------|
| Date of Inspection :   | 18.12.2020                                 | District:    | Aurangabad |
| Division :             | Aurangabad                                 | Length (km): |            |
| Name of the Road:      | NH-98 to Bapat Bigha                       |              |            |
| Scheme/Programme:      | MAINTENANCE                                | GT S N Y     |            |
| Package No.:           |                                            | Road ID No.: |            |
| Status of the Project: | Ongoing/Completed/Under Maintenance        |              |            |
| Work is a case of:     | New Connectivity/Up gradation/ Maintenance |              |            |

| Sl No. | Parameters to be checked                                                                                        | Remarks       |
|--------|-----------------------------------------------------------------------------------------------------------------|---------------|
| 1.     | Pavement                                                                                                        |               |
| a)     | Road Junction condition                                                                                         | ✓ S/U         |
| b)     | Condition of Surfacing                                                                                          | ✓ S/U         |
| c)     | Riding Quality                                                                                                  | ✓ S/U         |
| d)     | Road Camber                                                                                                     | ✓ S/U         |
| e)     | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                    | ✓ Yes/No      |
| f)     | Contraction Joints provided or not (CC Pavement)                                                                | ✓ Yes/No      |
| g)     | Compaction of flank/slope & raincuts if any                                                                     | ✓ Yes/No      |
| 2.     | Gross Drainage                                                                                                  |               |
| a)     | Condition of head walls in Hume pipe culverts including its painting                                            | S/SRI/U       |
| b)     | Condition of Abutment & Wing walls, Slab in RCC culverts                                                        | S/SRI/U       |
| c)     | Condition of railings/slab/approach for Bridges                                                                 | S/SRI/U       |
| 3.     | Road Furniture                                                                                                  |               |
| a)     | Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained | 200m ✓ Yes/No |
| 4.     | Compliance History                                                                                              |               |
| a)     | Status of ATR's & any others                                                                                    |               |

Overall Rating :

|                                             |     |
|---------------------------------------------|-----|
| Satisfactory (S)                            |     |
| Satisfactory but requires Improvement (SRI) | SRI |
| Unsatisfactory (U)                          |     |

- ① Maintenance Board Not found  
 ② Bushes in flank 0 to 300M  
 ③ Hair Cracks in pavement 100M to 300M

  
 (Signature)

NAME: Rajendra Prasad Khatwar  
 A.E. Aurangabad