

Inspection Report for Flood Damage Work

Date.:

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West

2. Name of Block – Kanti

3. Name of Road/Bridge – PWD Road To Barmatpur

A. for Road

1. Damage Location/Chainage : 0.420km

2. Damage Length : 4.75

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works : - Bricks Bat, Local sand, sand bags

ii. Equipments/Tools being used in Restoration Works : Tractor, Roller, JCB

iii. Procedure taken up in Restoration works :

iv. Restored Length : - 4.75

B. for Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works :


ii. Equipments/Tools being used in Restoration Works :

iii. Procedure taken up in Restoration works :

iv. Restored Length :


J.E.


A.E.


Executive Engineer,
R.W.D. Works Division,
Muzaffarpur west


Signature
(Name of Inspector)