

## Inspection Report for Flood Damage Work

Date.: .....

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West
2. Name of Block – Kanti
3. Name of Road/Bridge – Beriya Railway Gumti To Damodarpur


### A. for Road


1. Damage Location/Chainage : 0.050 km
2. Damage Length : 68.590 m
3. Nature of Damage :
4. Details of Restoration Works :
  - i. Material being used in Restoration works : Bricks Bat, Local sand
  - ii. Equipments/Tools being used in Restoration Works : Tractor, Roller, JCB
  - iii. Procedure taken up in Restoration works :
  - iv. Restored Length : - 68.590 m

### B. for Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
  - i. Material being used in Restoration works :
  - ii. Equipments/Tools being used in Restoration Works :
  - iii. Procedure taken up in Restoration works :
  - iv. Restored Length :

  
J.E.

  
A.E.

  
Executive Engineer,  
R.W.D. Works Division,  
Muzaffarpur west

  
Signature  
(Name of Inspector)