

Inspection Report for Flood Damage Work

Date.:

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West
2. Name of Block – Kanti
3. Name of Road/Bridge – Mithan Sarai Pusakalaya Ram Sevak shah ke ghar ke pas Mukhya Sadak to Jamalabad REO path tak via Gandak Bandh Aur Ramsomari Devi ke ghar hote hue


A. for Road


1. Damage Location/Chainage : 0.670 km
2. Damage Length : 101.00 m
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works : - Brick's Bat, Local sand
 - ii. Equipments/Tools being used in Restoration Works : Tractor, Roller, JCB
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length : - 101.00 m

B. for Bridge

1. Damage Location/Chainage : N/A
2. Damage Length : N/A
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration Works :
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :


J.E.


A.E.


Executive Engineer,
R.W.D. Works Division,
Muzaffarpur west


Signature
(Name of Inspector)