FIELD INSPECTION REPORT

Date of Inspection: 13/21			District: East clamperan		
Division: Raparel			Longth (km): 1.261		
Name of	the Road: PA	roed Chause	dano Nehor to Chaired	and Hallar	
Scheme/	Programme:	MAINTENANCE	and the second s		
Package No.:		The second secon	Road Id No.: 31708512022		
Status of the Project:		Ongoing/Completed/Under Maintenance			
Work is a case of:		New Connectivity/Up gradation/ Maintenance			
Sl. No.		Parameters to be checked		Remarks	
1.	Pavement				
a)	Road Junction condition			√ S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			√s/U	
d)	Road Camber			Sru	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
ſ)	Contraction Joints provided or not (CC Pavement)				
g)	Compaction of flank/slope & raincuts if any Yes/No				
2.	Cross Draina	ge			
a)	Condition of head walls in Hume pipe culverts including its painting AS/SRI/U				
b)	Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/U				
c)	Condition of railings/slab/approach for Bridges M. A. S/SRI/U			- S/SRI/U 	
3.	Road Furniture				
a)	Whether sign	boards/informatory ent road markings are	/cautionary_Board/km & 200m provided and maintained	Xes/No	
4.	Compliance History				
		R's & any others		N.A.	
3.	Road Furnitu Whether sign stones/Paveme Compliance I	ire boards/informatory ent road markings are History	/cautionary Board/km & 200m		

Overall Rating :

Satisfactory (S)	'51
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	

NAME:
DESIGNATION: JUNIOR Byines, Cheuredeno