FIELD INSPECTION REPORT

		FIELD INSPEC		and the second second	
Date of Inspection: 13.1.21 District: Cost			District: Cost clambar	au	
Division: Renaul			Length (km): 0.626		
Name	of the Road:	exariya to Pak	aria Tola	والمسترورة والمستنفع المدارات والمستنفض الدواو	
Packa	ge No.:		Road Id No.: 31708501		
Status of the Project:		Ongoing/Completed	/Under Maintenance	بالمراجع والمتحدد والمتحدد والمتحدد	
Work is a case of:		New Connectivity/Up gradation/ Maintenance		Remarks	
SI. No	Parameters to be checked				
1.	Pavement			5/U	
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			s/U	
c)	Riding Quality Read Complete A. A.			S/U	
d)	Road Cambel			Yes/No	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
1)	Contraction Joints provided or not (CC Pavement)			Yes/No	
	Compaction of flank/slope & raincuts if any			Yes/No 	
g)	a Disingu				
2.	Cross Drainage Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
a)	Condition of head walls in Flume pipe can be a Winn walls Slab in RCC culverts			S/SRI/U	
b)	Condition of Abatment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges 5/5K//0				
3.	Road Furniture			Vaa/Na	
a)	Whether sign boards/informatory/cautionary Board/km & 200m Yes/No stones/Pavement road markings are provided and maintained				
4.	Compliance History				
a)	Status of ATR's &	& any others			
<u>i</u>			7	(6/	

Overall Rating

	(51
Satisfactory (S))
Satisfactory but requires Improvement (SRI	
Unsatisfactory (U)	

(Signature)

aittilest komas singl

NAME:

cirior Egizer, Mayradano

DESIGNATION: