FIELD INSPECTION REPORT

Du	te of Inspection :	2-1-2021 100	ELIKEFORT :	
Division: Porthast		bethist to	District: w. Characteryon	
1	me of the Road:	and what is adularized	ngth (km): 0 - 7 %	
Pac	eme/Programme: kage No.:	MAINTENANCE	138 manua Dul to B)	randulia-
Stat	us of the Project:	Ros	nel Tel No.	
The state of the s		Ongoing/Completed/Und	or Main	2.10
SL	The same of the sa	Connectivity/Up gra	dation/ Maintenance	
-		Parameters to be ch	ccked	El Sylles State Company
1	Pavement			Remark
n)	Road Junction condition			The second
b)			S/U	
c)		Riding Quality		S/U
d)				
0)	Road Camber		S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Join	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of fi	Compaction of flank/slope & raincuts if any		
2.	Cross Drainage			Yes/No
2)	The second second second second	Lucius Consultation		
b)	Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U	
-	Condition of Abu	ment & Wing walls, Slab	in RCC culverts	S/SRI/U
c)	Condition of railing	gs/slab/approach for Bridg	ges	S/SRI/U
3	Road Furniture			UL SULES
)	Whether sign bostones/Pavement re	ards/informatory/cautionar ad markings are provided	y Board/km & 200m	Yes/No
99	Compliance Histo			V
1	Status of ATR's & any others		100 110	
-1		and a control		No

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	SRI

(Signature)

NAME: Radiato Persona Sum/dul

DESIGNATION: J-E & A-E

(32)

AG